


REPAIRS FOR NO. 8 DIRECT STROKE MILL

Windmill-Parts.com

Windmill-Parts.com



Windmill-Parts.com

940 597-7735

PART No.	NAME	10 Ft. No. 8	12 Ft. No. 8	PART No.	NAME	10 Ft. No. 8	12 Ft. No. 8
D 1	Main frame or oil reservoir	\$9.00	\$11.00	D 37	Splice iron, 2 pieces	.30	.60
D 2	Main frame cap	1.25	1.25	D 38	Cross head guide short	1.00	1.00
HS 2	Clamp for pipe frame	.80	1.00	D 39	Cross head guide long	1.25	1.25
D 3	Bearing sleeve	1.50	1.75		Oil dip for short cross head guide	1.00	1.00
D 4	Main shaft	2.50	3.00		Oil dip for long cross head guide	1.00	1.00
D 5	Nut for outer end of main shaft	.20	.30	D 40	Cross head	1.25	1.50
D 6	Oil retaining washer	.15	.20	D 41	Steel arm	1.25	1.80
D 7	Set collar	.50	.80	D 42	Guide clamp	.75	1.00
D 8	Oil carrying spring	.25	.30	D 43	Large sheave	.40	.40
D 9	Timken bearing cup	1.25	2.25	H 55	Lower guide	.70	1.00
D 10	Timken bearing cone	2.00	3.25	HH 74	Piston rod	1.00	1.25
D 11	Face plate	1.60	2.10	HHD 79	Pull-out chain	.45	.80
D 12	Wrist pin	.70	.80	D 89	Large spider	1.70	3.00
D 13	Cross head pin	.70	.80	D 90	Complete vane, steel	9.50	11.00
DS 14	Small spider	.75	1.00	D 90	Complete vane, wood	8.00	11.00
D 15	Steel pitman	2.00	2.25	D100	Wheel section, steel	3.00	4.50
	Bronze bushings for pitman	.40	.40	D100	Wheel section, wood	4.00	5.50
D 16	Brake lever	.75	1.00	D101	Cover over engine or hood	2.50	2.50
D 17	Brake band	.70	1.00	H102	Wood rod connection	.60	1.00
D 18	Brake adjusting casting	.40	.50	H103	Cross head swivel clamp	.25	.25
D 20	Bumper spring and casting	.40	.80	H104	Upper end of pull-out swivel	.50	.50
D 21	Regulating spring	1.00	2.00	H105	Lower end of pull-out swivel	.60	.70
D 22	Spring bar	.40	.60	H106	Pull-out rod	.50	.60
D 23	Small sheave	.40	.40	H107	Stop rod for pull-out swivel	.25	.25
D 24	Sheave guard	.50	.50	HD108	Complete pull-out less mast pipe	5.00	7.00
D 25	Outside end wheel clip	.50	.50		Box bolts for steel wheel	2.50	3.00
D 26	Inside end wheel clip	.30	.30		Box bolts for wood wheel	2.00	2.50
D 27	Wheel clip	.40	.40		Pull-out chain, per foot	.12	.12
D 28	Pin for large sheave	.10	.10		1/2 inch steel balls each	.025	.025
D 29	Tower cap clamp	.20	.20		Wood rod per 100 ft.	4.40	4.40
D 30	Steel tower storm stay	1.50	2.00		3/8 x 1 Galv. mach. bolts, each	.04	.04
D 31	Steel or wood tower storm stay	1.50	2.00		Steel blades for section	.60	.60
D 32	Fairbury steel tower cap	1.50	2.00		Small steel wheel clips	.05	.05
D 34	Crank pin washer	.10	.10		Large steel wheel clips	.10	.10
D 35	Vane hinge pin	.50	.75				
D 36	Mast pipe	1.60	3.00				