

DEMPSTER NO. 1 VANELESS WINDMILL

REPAIRS




Fig. 900

This mill is not made now, but we can furnish repairs.

See Next Page for Price List.

Windmill-Parts.com  
940 597-7735

Windmill-Parts.com  
940 597-7735

DEMPSTER VANELESS NO. 1 WINDMILLS

REGULAR STROKE AND LONG STROKE

PRICE LIST OF REPAIRS

(Cut on Preceding Page)

ITEM	10-ft. L. Stroke		12-ft. L. Stroke		10-ft. Regular		12-ft. Regular	
	No.	List	No.	List	No.	List	No.	List
Top Casting.....	1G	\$5.00	1H	\$6.00	1G	\$5.00	1H	\$6.00
Main Stem.....	2G	5.00	2H	6.00	2G	5.00	2H	6.00
Two-post Turntable.....	3G	2.50	3H	4.30	3G	2.50	3H	4.30
Clip on Step.....	4G	.15	4H	.20	4G	.15	4H	.20
Two-post Step.....	5G	1.60	5H	2.50	5	1.60	5H	2.50
Arm Casting.....	6	.10	6X	.15	6	.10	6X	.15
Fan Casting.....	7	.10	7X	.10	7	.10	7X	.10
Fan Hinge.....	8	.15	8X	.20	8	.15	8X	.20
Swivel Casting.....	7G	.30	7G	.30	7G	.30	7G	.30
Swivel Casting.....	8G	.30	8G	.30	8G	.30	8G	.30
Face Plate.....	9G	1.60	9H	3.00	9	1.40	9	2.70
Bottom of Clutch Box.....	13	.50	13	.50	13	.50	13	.50
Top of Clutch Box.....	14	.50	14	.50	14	.50	14	.50
Spider.....	15G	2.50	15H	3.50	15G	2.50	15H	3.50
Sliding Boss.....	17G	1.70	17H	1.80	17G	1.70	17H	1.80
Traveler.....	19G	.30	19H	.30	19G	.30	19H	.30
Pin for Traveler.....	19 1/2 G	.10	19 1/2 H	.10	19 1/2 G	.10	19 1/2 H	.10
Pump Connection.....	20	.50	20	.50	20	.50	20	.50
Splice Irons, per pair.....	21	.50	21	.50	21	.50	21	.50
Top Box.....	21G	.80	21H	.80	21G	.80	21H	.80
Wheel Weight.....	22B	.75	22C	1.00	22B	.75	22C	1.00
Top Box.....	23G	.60	23H	.70	23G	.60	23H	.70
Weight Bar Fulcrum.....	25G	.50	25H	.80	25G	.50	25H	.80
Cross Bar.....	28G	.80	28F	.90	28	.50	28F	.60
Regulating Weight.....	29	1.50	29	1.50	29	1.50	29	1.50
Set Collar.....	30G	.60	30H	.60	30G	.60	30H	.60
Wrist Pin Only.....	32G	.70	32H	.70	32G	.70	32H	.70
Wrist Pin with Nut and Washer.....	32G	.90	32H	.90	32G	.90	32H	.90
Slide Head Rod.....	33G	.50	33H	.60	33G	.50	33H	.60
Main Shaft.....	34G	2.50	34H	3.75	34G	2.50	34H	3.75
Shifting Rod.....	35G	.80	35H	1.00	35G	.80	35H	1.00
Weight Bar.....	36G	.75	36H	.75	36G	.75	36H	.75
Section Rod.....	37G	.25	37H	.30	37G	.25	37H	.30
Step for W. T.....	40G	2.00	40H	2.70	40G	2.00	40H	2.70
Turntable for W. T.....	41G	2.70	41H	3.40	41G	2.70	41H	3.40
Turntable for S. T.....	42G	2.70	42H	3.40	42G	2.70	42H	3.40
Step for S. T.....	43G	2.40	43H	3.00	43G	2.40	43H	3.00
Pitman.....	51G	1.00	51H	1.20	51G	1.00	51H	1.20
Guide Casting.....	52G	.70	52H	.80	52G	.70	52H	.80
Pitman Connection.....	53	1.00	53	1.20	53	1.00	53	1.20
Guide for Flat Bar.....	57G	.30	57H	.30	57G	.30	57H	.30
Balance Weight (horse).....	58G	2.20	58G	2.50	58G	2.20	58H	2.50
Rod for 40 G Step.....	59G	.15	59G	.15	59G	.15	59G	.15
Flat Bar.....	60G	1.20	60H	1.40	60G	1.20	60H	1.40
Guide Roller.....	61G	.20	61G	.20	61G	.20	61G	.20
Wood Pitman Box.....	62G	.25	62H	.30	62G	.25	62H	.30
Staple and Clip.....	63G	.10	63H	.15	63G	.10	63H	.15
Babbitt Half Box.....	64	.30	64	.30	64	.30	64	.30
Large Washer for W. P.....	65G	.15	65H	.15	65G	.15	65H	.15
Lower Pitman Pin.....	66	.20	66	.20	66	.20	66	.20
Swivel Casting.....	66G	.50	66G	.50	66G	.50	66G	.50
Swivel for Pull Out Rod.....	67	.10	67	.10	67	.10	67	.10
Nut for Wrist Pin.....	68	.10	68	.10	68	.10	68	.10
Small Washer for W. P.....	69	.05	69	.05	69	.05	69	.05
Spring Cotter for W. P.....	70	.02	70	.02	70	.02	70	.02
Bar for Balance Weight.....	71G	1.50	71H	1.60	71G	1.50	71H	1.60
Wood Wheel Arm.....	72G	.85	72H	1.00	72G	.85	72H	1.00
Wood Pull Out Lever.....	73	.50	73	.50	73	.50	73	.50
Steel Washer for Step.....	74G	.15	74H	.30	74G	.15	74H	.30
Wood Wheel Rib, short.....	75G	.30	75H	.40	75G	.30	75H	.40
Wood Wheel Rib, long.....	76G	.40	76H	.50	76G	.40	76H	.50
Wood Wheel Slat.....	77G	.10	77H	.15	77G	.10	77H	.15
Wood Wheel Section.....	78G	3.00	78H	3.75	78G	3.00	78H	3.75
Weight Box.....	86J	1.50	86J	1.50	86J	1.50	86J	1.50
Weight Box Lid.....	87J	1.00	87J	1.00	87J	1.00	87J	1.00
Wood Actuat'g R'd, 16-ft. lgh.....		.50		.50		.50		.50

Windmill-Parts.com  
940 597-7735