

DEMPSTER VANELESS NO. 3 WINDMILLS
REPAIRS




Fig. 1147

NO. 3 VANELESS WINDMILL REPAIRS (Continued)

Description	No.	10-ft.	No.	12-ft.
Swivel Casting	66G	\$0.50		
Upper Pitman Pin	66JJ	.50	66YY	\$0.60
Nut for Wrist Pin	68	.05	68	.05
Balance Weight Bar, right	71J	1.50	71Y	1.60
Balance Weight Bar, left	71½J	1.50	71½Y	1.60
Wheel Arm	72J	.85	72Y	1.00
Wood Pull Out Lever	73	.50	73	.50
Wood Wheel Ribs, short	75J	.30	75Y	.40
Wood Wheel Ribs, long	76J	.40	76Y	.50
Wood Wheel slats	77	.10	77	.15
Wood Wheel Sections	78J	3.00	78Y	3.75
Fan Weight	79J	.20	79J	.20
Guide Casting	79½	.60	79½Y	.80
Angle Iron	80JJ	.30	80YY	.40
Wheel Brace	81J	.25	81Y	.30
Staple for No. 23	82J	.15	82Y	.20
Truss Rod	83JJ	.20	83YY	.30
Guide Rod for No. 24	84JJ	.15	84YY	.20
Eye Bolt for Pull Out Lever	85	.10	85	.10
Weight Box	86J	1.50	86J	1.50
Weight Box Lid	87J	1.00	87J	1.00
Cast Washer	88JJ	.10	88JJ	.10
Cap for Upper Guide	89JJ	.20	89YY	.20
Brace for Horse Weight Bar	90JJ	.40	90YY	.50
Main Frame Stem			91YY	6.60
Slide Bearing			92Y	.60
Corner Bearing	Don't Use		109	.90
Corner Washer, S. T.	109	.06	109	.90
Square Bar	145JJ	3.00	145YY	4.50
Bed Plate, W. T.	411	1.05	90C	1.80
Swivel			414B	1.50
Swivel Box			415B	2.10
Swivel Box Cap			416B	2.10

DEMPSTER VANELESS NO. 3 WINDMILLS

REPAIRS AND PRICE LIST

Description	Ten-Foot		Twelve-Foot	
	No.	List	No.	List
Guide Casting	0J	\$0.80	0Y	\$0.90
Clamp for Main Stem.....	Don't Use		1½ YY	1.80
Top Casting	1JJ	7.65	1YY	8.75
Arm Casting	6½	.30	6½ X	.35
Fan Hinge, right.....	8½	.20	8½ X	.25
Fan Hinge, left.....	08½	.20	08½ X	.25
Swivel Casting	7G	.30		
Swivel Casting	8G	.30		
Face Plate	9J	1.60	9Y	2.20
Large Spider	15J	2.70	15Y	3.00
Plate for Large Spider.....	15½ J	.40	15½ Y	.50
Small Spider	16J	.50	16Y	.70
Storm Stay, W. T.....	16	1.00	16U	1.50
Pump Connection	20A	.50	20A	.50
Splice Irons, per pair.....	21	.50	21½	.80
Top Box	21J	.60	21Y	.70
Wheel Weight	22	.75	22C	.90
Top Box	23J	.60	23Y	.70
Sliding Boss Complete.....	24J	.40	24Y	.60
Top Clutch Box.....	25J	.60	25Y	.70
Bottom Clutch Box.....	26J	.50	26Y	.60
Regulating Weight	29	1.40	29X	2.00
Wrist Pin	32JJ	.70	32YY	1.00
Slide Head Rod.....	33JJ	.55	33YY	.70
Main Shaft	34J	2.30	34Y	2.70
Shifting Rod	35J	.40	35Y	.60
Weight Bar	36JJ	1.20	36YY	1.35
Section Rod	37	.25	37Y	.30
Cast Roller	38JJ	.10	38JJ	.10
Wood Pitman	51JJ	1.10	51YY	1.25
Bed Plate, S. T.....	57B	1.20	57C	1.70
Storm Stay, S. T.....	58BB	1.00	58½ U	1.50
Horse Weight	58G	1.80	58G	1.80
Staple and Clip for No. 22.....	63	.10	63	.10
Sabbitt Box	64J	.40	64Y	.60

Windmill-Parts.com
 940 597-7735