



Windmill-Parts.com
940 597-7735

REPAIRS

FOR

NO. 6

WORM

GEARED

Windmill-Parts.com

940 597-7735

MILL

Windmill-Parts.com

940 597-7735

PART NO.	NAME	8 Ft. No. 6	10 Ft. No. 6	PART NO.	NAME	8 Ft. No. 6	10 Ft. No. 6
11	Sheave for pull out chain	.40	.40	73	Wood brake shoe	.25	.25
12	Sheave or pulley holder	.55	.55	74	Piston flat bar	1.00	1.00
14	Small spider	.75	.75	75	Pull out rod	.50	.50
17	Wood tower cap, eclipse pattern	1.50	1.50	76	Regulating spring	.90	1.00
21	Swivel clamp	.30	.30	77	Short double eyed rod for spring	.35	.40
22	Lower end of swivel	.85	.85	78	Short chain for spring	.15	.15
23	Upper end of swivel	.55	.55	79	Pullout chain	.45	.45
37	Wood rod to pump connection	.60	.60	80	Arm for wheel	.90	1.25
38	Cast clamp or washer	.20	.20	81	Large half of main frame	5.60	6.75
W 38	Wood clamp or washer	.15	.15	82	Small half of main frame	3.95	4.50
48	Wood tower storm stay	1.50	1.50	83	Clamp for main frame	.80	.80
E 48	Combination storm stay	1.50	1.50	84	Walking beam	2.25	2.80
S 48	Steel tower storm stay	1.50	1.50	85	Vane hinge	2.25	2.25
E 49	Combination tower cap	1.50	1.50	86	Brake lever	1.10	1.40
S 49	Fairbury steel tower cap	1.50	1.50	87	Coupler, walking beam to piston	.55	.85
48	Wood tower step plate	1.50	1.50	88	Crank for each end of gear shaft	.90	.90
E 48	Old style steel tower step plate	1.50	1.50	89	Large spider for wheel	1.70	1.70
S 48	New style steel tower step plate	1.50	1.50	90	Gear and shaft	4.50	5.00
E 49	Wood tower cap	1.50	1.50	91	Worm and shaft	5.05	5.60
S 49	Steel tower cap	2.00	2.00		Gear less shaft	3.95	4.50
55	Lower guide	.70	.70		Worm less shaft	4.50	5.00
60	Roller for brake lever	.15	.15	92	Stud pin for cranks	.60	.60
61	Short key for crank	.20	.20	93	Complete vane less pipe and springs	6.00	9.00
62	Long key for spider	.20	.20	94	Crooked arm to which spring fastens	1.10	1.10
63	Stud pin washer	.10	.10	95	Cross shaft for pitmans	1.10	1.10
64	Cross shaft washer	.20	.20	96	Short pin for walking beam	.55	.55
65	Truss rod	.55	.75	97	Long pin for walking beam	.55	.55
66	Upright pipe	1.60	1.60	98	Long pin for vane hinge	.50	.50
67	Vane pipe	2.00	2.50	99	Wood pitman	.80	.80
68	Bumper spring and casting	.40	.40	100	Complete section	2.45	3.00
69	Oil cup	.55	.55		Complete set wood boxings	2.65	2.65
70	Half of long wood box	.85	1.00		Steel blades for sections	.60	.60
71	Half of short wood box	.65	.85		Small wheel clips	.05	.05
72	Solid wood box in steel sleeve	1.10	1.10		Large wheel clips	.10	.10
					3-8x1 galvanized bolts, each	.04	.04